

Cross Check™

Torque Seal® Tamper-Proof Indicator Paste

HANDLING

- Obtain special instructions before use.
- Do not handle until all safety precautions have been readand understood.
- Do not handle, store or open near an open flame, sources of heat or sources of ignition.
- Protect material from direct sunlight. Explosion-proof

DIRECTIONS

- DRY TIME: Dry to touch/handle in 30-40 minutes.
- 80% curing occurs between 48-72 hours. Completion of curing takes place between 7-10 days.
- Exposing to elevated temperature OR blowing hot air can speed up the drying/curing process.

STORAGE

• Store locked up. Keep away from heat, sparks and open flame. Prevent electrostatic charge build-up by using common bonding and grounding techniques. Store in a cool, dry place out of direct sunlight. Store in tightly closed container. Store in a well-ventilated place. Keep in an area equipped with sprinklers. Store away from incompatible materials (see Section 10 of the SDS).

DISPOSAL

 Collect and reclaim or dispose in sealed containers at licensed waste disposal site. Dispose ofcontents/container in accordance with local/regional/national/international regulations.

FEATURES

- Tamper Proof Torque Mark
- Safe for most surfaces
- Highly visible- blue, yellow, red, green, and orange colors are fluorescent under blacklight
- Excellent adhesion
- Visually detects loose nuts & bolts
- Provides warranty protection
- Meets BOEING Specification, BMS8-45 Type II



PHYSICAL PROPERTIES

Appearance / Physical State	Liquid
Odor	mild
Flash Point	105.1 °F (40.6 °C)
Boiling Point / Range	276.98 - 485.06 °F (136.1 - 251.7 °C
VOC Content	42.28%, 430 g/L
Vapor Density	> 1 (air = 1)
Prop 65 Warning	YES

AVAILABLE IN

Color	Net	Cnt.	Units/	Part #	
	Contents	Type	Case	US	Canada
orange	1 oz	tube	24	83314	C83314
green	1 oz	tube	24	83315	
red	1 oz	tube	24	83316	C83316
yellow	1 oz	tube	24	83317	C83317
blue	1 oz	tube	24	83318	C83318
white	1 oz	tube	24	83319	C83319
pink	1 oz	tube	24	83320	C83320
gray	1 oz	tube	24	83321	